

Work Control Pack



1.1 Basic Information	n Pack	Ref: WC	P792 Issu	ie no: 1	Job no:	į.	
Title Calibration of proton detector in the MAST area using an unsealed source							
Description of Work The proton detector is a probe mounted on the MAST reciprocating probe system. This work pack is to cover the task of calibration of the proton detector electronics using an unsealed Americium 241 source (MPR-alpha 1).							
Location of Work Reciprocating probe, MAST ar			ST area, D1.	D1. Quality Class N/A (if applicable)			
Impact on other syste	ms No	ne					
1.2 Documentation Required Please tick ☑							
Risk Assessment(s) Ref: 82216							
Method Statement(s) Ref:		MS216 I	MS216 Issue 1			han a said and a said	
Workforce Endorsement			Tr	Hot Work Permit			
Hazard Identification Checklist				Mechanical Is	solation Certificate	ion Certificate	
Contractor Risk Assessment Evaluation Form				Permit to Wo	rk on Electical Equipment	n Electical Equipment	
Hazardous Substances Risk Assessment				Sanction for T	Test - Electrical	- Electrical	
Manual Handling Assessment				Electrical Isol	ation Certificate	n Certificate	
Health Physics Certificate / IRR local rules				Isolation Certi	ificate - High Voltage	te - High Voltage	
Lifting Plan				Permit to Test	t Equipment	Equipment	
Waste Management Interface (WMI) Form Approved				Excavation Certificate / Permit			
Welding Pack				Other:			
Other:				Other:			
1.3 Techical Interfac	e Revie	W RO to	note reviev	vers who were c	onsulted		
Name Post Held				Technical Review Completed			
Etienne Letellier Health Physics			ics	To the second se			
Gerry O'Sullivan MAST Radiation I			ition Protect	tion Officer			
Mike Driscoll MAST ATO Holde			Holder				
		CONTRACTOR OF THE PARTY OF THE		<u>, e e , , qui maga a qua assessa trasses trasses de la companya d</u>			
1.4 Checking of Pag	:k	The first transfer of	· · · · · · · · · · · · · · · · · · ·				
Prepared by Name: Scott Allan				Signature: Date:		ie:	
RO signs to confirm all technical interfaces have been consulted							
Checked by Name: Mike Driscoll				Signature: Date:		ie:	
(Line Manager or Nominee)				Signatural		· ·	
RO Undertaking Scott Allan Work Name:				Signature: Date:		e:	
RO undertaking work signs to	confirm Pa	ck is approp	oriate. RO	btains authoris	ation & briefs workforce.		